SOUTH DELHI MUNICIPAL CORPARATION OFFICE OF THE DEPUTY HEALTH OFFICER, CENTRAL ZONE JAL VIHAR, SHIV MANDIR MARG, NEW DELHI-24

No: DHO/CNZ/2022/D-1379

Dated: 07/02/2012

HEALTH CERTIFICATE

1. Name of the school

NALANDA CONVENT SCHOOL

2. Address of the school

D-5, SCHOOL ROAD, OM NAGAR, NEW DELHI-

15

110044

3. Shift

Morning

4. No. of student

Boys: 115

Girls:

132 Total: 247

5. No. of staff

Gents: 03

Ladies:

Total: 18

6. Accommodation provided are as under:-

- Floor areas in the classrooms are sufficient.
- Classrooms are well ventilated and well lighted.
- Classrooms are kept neat and clean.
- Building/Classrooms do not require white wash.
- Drinking water is wholesome.
- Latrine arrangement is sanitary.
- Number of Latrines and Urinals are sufficient.
- Separate toilet arrangements for Boys & Girls are present.
- Separate toilet arrangement for staff is present.
- The overall facilities are adequate.

Dy. Health Officer Central Zone

> Dy. Health Officer Central Zone, SDMC

Remark: This certificate is valid up to one year from date of issue and has no bearing on structural stability and unauthorized construction in the school premises

"STOP CORONA VIRUS-Wash Your Hand/Wear Mask/Maintain Social Distance"



OFFICE OF THE ACWA (RWS) DELHI JAL BOARD (GOVT. OF N.C.T. DELHI) QUALITY CONTROL DIVISION, **BOTTLING PLANT GREATER KAILASH, NEWDELHI-110048**



Dated:-30/12/2021

Analysis Report of water sample collected from:- M/S Nalanda Convent School, D-5, School Road,

Permissible

Method of

Om Nagar, Badarpur, New Delhi-110044, Vide Challan No.-214 dated-24.12.2021. Water Cooler, Nr. Nursery Class room, Ground Floor

Requirement

(i) Direct supply at roof top tank (ii)

S.No.	PARTICULARS	(Acceptable Limit)	Limit in the absence of alternate source	Test, Ref to part of IS- 3025	RESULTS	
		PHYS	CAL EXAMIN	NATION		
		- 11110	The state of the s	1	(i)	(ii)
					28.12.2021	28.12.2021
1.	Date of Collection	5 HU	15 HU	Part-4	Clear	Clear
2.	Clarity/Colour		Agreeable	Part-5	Agreeable	Agreeable
3.	Odour	Agreeable	Agreeable	Part-7 and 8	Agreeable	Agreeable
4.	Taste	Agreeable	5.0 NTU	Part-10	1.30	1.75
5,	Turbidity	1.0 NTU	No relaxation	Part-11	7.68	7.54
6.	pH Value	6.5-8.5	Service and	A STATE OF THE STA	384	363
7.	Conductivity			Part-16	250	234
8.	T.D.S.	500 mg/L	2000 mg/L	Partition		
	IICAL EXAMINATION				NIL	NIL
	P th Alkalinity as CaCO ₃	••			106	98
9.	Total Alkalinity as CaCO ₃	200 mg/L	600 mg/L	Part-23	134	130
10.	Total Hardness as CaCO ₃	200 mg/L	600 mg/L	Part-21		98
11.	Carbonate Hardness		,		106	32
12.	Non Carbonate Hardness				28	84
13.			••	Part-40	86	46
14.	Calcium Hardness		,	Part-46	48	33.6
15.	Magnesium Hardness	75 mg/L	200 mg/L		34.4	
16.	Calcium as Ca	30 mg/L	100 mg/L		11.52	11.04
17.			No relaxation	Part-34	NIL	NIL
18.	Ammonia (as N)	0.5 mg/L	10 10,0,00	Part-34	NIL	NIL
19.	Nitrite (as N)		No relaxation	Part-34	6.67	6.33
20.	4 210 1	45 mg/L	140 Telanation			

Sulphate (as SO ₄) 200 mg/L Chloride (as Cl) 250 mg/L Iron (as Fe) 0.3 mg/L Fluoride (as F) 1.0 mg/L Free Residual Chlorine 0.2 mg/L	400 mg/L 1000 mg/L 1.0 mg/L 1.5 mg/L 1.0 mg/L	Part-24 Part-32 Part-53 Part-60 Part-26	40.2 32 00.02 0.38 NIL	32.4 32 0.02 0.26 NIL
--	---	---	------------------------------------	-----------------------------------

Remark: On the basis of tested parameter, both water samples confirm to the drinking water specification, IS-10500-2012, hence fit for drinking purpose after proper chlorination/disinfection.

Juny 11 2017

ASSTT. CHEMIST

CHEMIST

ACWA 01/22

<u>DELHI JAL BOARD</u>

GOVT. OF NCT OF DELHI RURAL WATER SUPPLY LABORATORY SOUTH, GK-I, NEW DELHI-48

Date:-30/12/2021

3acteriologica	l Anal	ysis	Report

Ref:-DJB/DTQC/ACWA, RWS (SOUTH) P.S. (Bact.)/P1 & P2

M/s Nalanda Convent School D/5, School road Om Nagar, Badarpur, New Delhi-110044

Party's ref. & Date: NIL

Dept Challan No. & Date: 214 & 24/12/2021

Date of sample collection: 28/12/2021

Reported on dated: 3<u>0/12/2021</u> No. of sample(s): TWO (02)

Note: Coliform count at 37°C/100 ml after 48 Hrs.

S.No.	Particulars	Clarity	Residual chlorine Mg/L	MPN 100 ml
record	d floor page nursery class root	m Clear	N.D	20
P1	Tap at water cooler, ground floor near nursery class root Nalanda Convent School.			210
P2	Tap at Syntex tank on roof top of Nalanda Convent scho	ol. Clear	N.D	210

Remarks: The collected water samples(P1 & P2) found unsatisfactory in bacteriological examination.

Asstt. Bacteriologist

ACWA (RWS&BP)